

**Triangle
Tube**



Warning

Maxi-Flo stainless steel heat exchangers are NOT suitable for pools and spas with aggressive water, salt water, or where a salt chlorinator is used. Warranty for such installations is NULL and VOID.

We recommend the use of our Titanium heat exchanger models for all installations noted above.

**Standard Limited Warranty
Against defects in material and workmanship:**

Stainless steel MF models – One Year

Titanium T models – Two Year